


## Zekler 1300 Series

EN	Particulate filtering half mask
SV	Partikelfiltrerande hälsmask
DA	Partikelfiltrerende halmask
NO	Partikelfiltrerende halmask
FI	Hukkasiututtava pudinaamari
FR	Demi-masque filtrant contre les particules
DE	Partikelfiltrierende Halmask
ET	Partikelsiitavat puhashinis
LT	Dalelių filtras puskaučiai
IT	Semifacciale filtriante per polveri
LV	Pusmaska (dien) filtrēšanai
IS	Augsstofslitninga
NL	Deelmaskfilterende halfmasker
PL	Półmaska z filtrem cząstek stałych


Full instructions for use in all languages: [www.zekler.com/fiu](http://www.zekler.com/fiu)

**Zekler Safety**  
52385 Ulrichshamn  
Sweden  
Phone +46 321 506 00  
info@zekler.com  
www.zekler.com

**Notified body:**  
involved in type approval:  
Institut für Arbeitsschutz der Deutschen gesetzlichen Unfallversicherung (IFA)  
Alte Heerstraße 111

53757 Sankt Augustin  
Germany  
Reference number: CE 0121  
DKR Testing and Certification GmbH  
Handwerkstr. 15  
70565 Stuttgart  
Germany  
Reference number: CE 0158

39 50 516 - © Zekler Safety  
Edition 03 - November 2023 - Subject to alteration



## EN - Instructions for Use

## For your safety

Strictly follow the Instructions for Use

Any use of the particle filtering half masks requires full understanding and strict observation of these instructions for use. The particle filtering half masks are only to be used for the purpose specified here. In case of queries please contact your safety officer, or us or see AS/NZS 2029.

**Description**  
The Zekler 1300 series includes the following particle filtering half masks (hereafter also called "half masks"):

- Zekler 1300, protection class FFP2
- Zekler 1300, protection class FFP3

Meanting of the markings: "NIR" means that the particle filtering half mask may only be used for a maximum of one work shift (8 hours).

Leverage having passed the Dolomite clogging test against clogging.

Some Zekler 1300 have an evaluation value ("V"), making exhaling easier.

**Intended use**



The particle filtering half masks are only to be used for the purpose specified here. Misuse can cause illness or death!

The particle filtering half masks require full understanding and strict observation of these instructions for use. The particle filtering half masks are only to be used for the purpose specified here. In case of queries please contact your safety officer, or us or see AS/NZS 2029.

**Limitations in the intended use**

The half mask must not be used as protection against gases, vapours or chemical, biological, radioactive and nuclear warfare agents.

The oxygen content of the ambient air must not drop below the following limit values:

10 vol.-% in Europe except UK, Ireland, Poland, Italy, Spain, Portugal, Belgium, UK, Australia and New Zealand.

For other countries, see the national regulations

Never enter unventilated tanks, pits, canals etc. when wearing half masks.

The half masks may be used for a maximum one work shift (8 hours) at a time.

The chapter "Additional information" contains recommendations for use against infectious germs and biologically harmful substances is possible. Information on this topic is either contained in the instructions for use or the relevant national regulations.

The maximum concentration of the pollutants (esp. the type and concentration of pollutants) must be known. The maximum permitted concentration of the pollutants in the ambient air must not be exceeded.

Observe the limit values and limitations of use for the various half masks:

The half masks have been tested and approved in accordance with (EU) 2016/425 and EN 149-2001+A1+At 2009.

Information on conformity: see [www.zekler.com/doc](http://www.zekler.com/doc)

They need to be worn against solid and liquid nonvolatile particles that do not exceed the amount of particles in the inhalable dust.

Limitations in the intended use

The half mask must not be used as protection against gases, vapours or chemical, biological, radioactive and nuclear warfare agents.

The oxygen content of the ambient air must not drop below the following limit values:

10 vol.-% in Europe except UK, Ireland, Poland, Italy, Spain, Portugal, Belgium, UK, Australia and New Zealand.

For other countries, see the national regulations

Never enter unventilated tanks, pits, canals etc. when wearing half masks.

The half masks may be used for a maximum one work shift (8 hours) at a time.

The chapter "Additional information" contains recommendations for use against infectious germs and biologically harmful substances is possible. Information on this topic is either contained in the instructions for use or the relevant national regulations.

The maximum concentration of the pollutants (esp. the type and concentration of pollutants) must be known. The maximum permitted concentration of the pollutants in the ambient air must not be exceeded.

Observe the limit values and limitations of use for the various half masks:

The half masks have been tested and approved in accordance with (EU) 2016/425 and EN 149-2001+A1+At 2009.

Information on conformity: see [www.zekler.com/doc](http://www.zekler.com/doc)

They need to be worn against solid and liquid nonvolatile particles that do not exceed the amount of particles in the inhalable dust.

Limitations in the intended use

The half mask must not be used as protection against gases, vapours or chemical, biological, radioactive and nuclear warfare agents.

The oxygen content of the ambient air must not drop below the following limit values:

10 vol.-% in Europe except UK, Ireland, Poland, Italy, Spain, Portugal, Belgium, UK, Australia and New Zealand.

For other countries, see the national regulations

Never enter unventilated tanks, pits, canals etc. when wearing half masks.

The half masks may be used for a maximum one work shift (8 hours) at a time.

The chapter "Additional information" contains recommendations for use against infectious germs and biologically harmful substances is possible. Information on this topic is either contained in the instructions for use or the relevant national regulations.

The maximum concentration of the pollutants (esp. the type and concentration of pollutants) must be known. The maximum permitted concentration of the pollutants in the ambient air must not be exceeded.

Observe the limit values and limitations of use for the various half masks:

The half masks have been tested and approved in accordance with (EU) 2016/425 and EN 149-2001+A1+At 2009.

Information on conformity: see [www.zekler.com/doc](http://www.zekler.com/doc)

They need to be worn against solid and liquid nonvolatile particles that do not exceed the amount of particles in the inhalable dust.

Limitations in the intended use

The half mask must not be used as protection against gases, vapours or chemical, biological, radioactive and nuclear warfare agents.

The oxygen content of the ambient air must not drop below the following limit values:

10 vol.-% in Europe except UK, Ireland, Poland, Italy, Spain, Portugal, Belgium, UK, Australia and New Zealand.

For other countries, see the national regulations

Never enter unventilated tanks, pits, canals etc. when wearing half masks.

The half masks may be used for a maximum one work shift (8 hours) at a time.

The chapter "Additional information" contains recommendations for use against infectious germs and biologically harmful substances is possible. Information on this topic is either contained in the instructions for use or the relevant national regulations.

The maximum concentration of the pollutants (esp. the type and concentration of pollutants) must be known. The maximum permitted concentration of the pollutants in the ambient air must not be exceeded.

Observe the limit values and limitations of use for the various half masks:

The half masks have been tested and approved in accordance with (EU) 2016/425 and EN 149-2001+A1+At 2009.

Information on conformity: see [www.zekler.com/doc](http://www.zekler.com/doc)

They need to be worn against solid and liquid nonvolatile particles that do not exceed the amount of particles in the inhalable dust.

Limitations in the intended use

The half mask must not be used as protection against gases, vapours or chemical, biological, radioactive and nuclear warfare agents.

The oxygen content of the ambient air must not drop below the following limit values:

10 vol.-% in Europe except UK, Ireland, Poland, Italy, Spain, Portugal, Belgium, UK, Australia and New Zealand.

For other countries, see the national regulations

Never enter unventilated tanks, pits, canals etc. when wearing half masks.

The half masks may be used for a maximum one work shift (8 hours) at a time.

The chapter "Additional information" contains recommendations for use against infectious germs and biologically harmful substances is possible. Information on this topic is either contained in the instructions for use or the relevant national regulations.

The maximum concentration of the pollutants (esp. the type and concentration of pollutants) must be known. The maximum permitted concentration of the pollutants in the ambient air must not be exceeded.

Observe the limit values and limitations of use for the various half masks:

The half masks have been tested and approved in accordance with (EU) 2016/425 and EN 149-2001+A1+At 2009.

Information on conformity: see [www.zekler.com/doc](http://www.zekler.com/doc)

They need to be worn against solid and liquid nonvolatile particles that do not exceed the amount of particles in the inhalable dust.

Limitations in the intended use

The half mask must not be used as protection against gases, vapours or chemical, biological, radioactive and nuclear warfare agents.

The oxygen content of the ambient air must not drop below the following limit values:

10 vol.-% in Europe except UK, Ireland, Poland, Italy, Spain, Portugal, Belgium, UK, Australia and New Zealand.

For other countries, see the national regulations

Never enter unventilated tanks, pits, canals etc. when wearing half masks.

The half masks may be used for a maximum one work shift (8 hours) at a time.

The chapter "Additional information" contains recommendations for use against infectious germs and biologically harmful substances is possible. Information on this topic is either contained in the instructions for use or the relevant national regulations.

The maximum concentration of the pollutants (esp. the type and concentration of pollutants) must be known. The maximum permitted concentration of the pollutants in the ambient air must not be exceeded.

Observe the limit values and limitations of use for the various half masks:

The half masks have been tested and approved in accordance with (EU) 2016/425 and EN 149-2001+A1+At 2009.

Information on conformity: see [www.zekler.com/doc](http://www.zekler.com/doc)

They need to be worn against solid and liquid nonvolatile particles that do not exceed the amount of particles in the inhalable dust.

Limitations in the intended use

The half mask must not be used as protection against gases, vapours or chemical, biological, radioactive and nuclear warfare agents.

The oxygen content of the ambient air must not drop below the following limit values:

10 vol.-% in Europe except UK, Ireland, Poland, Italy, Spain, Portugal, Belgium, UK, Australia and New Zealand.

For other countries, see the national regulations

Never enter unventilated tanks, pits, canals etc. when wearing half masks.

The half masks may be used for a maximum one work shift (8 hours) at a time.

The chapter "Additional information" contains recommendations for use against infectious germs and biologically harmful substances is possible. Information on this topic is either contained in the instructions for use or the relevant national regulations.

The maximum concentration of the pollutants (esp. the type and concentration of pollutants) must be known. The maximum permitted concentration of the pollutants in the ambient air must not be exceeded.

Observe the limit values and limitations of use for the various half masks:

The half masks have been tested and approved in accordance with (EU) 2016/425 and EN 149-2001+A1+At 2009.

Information on conformity: see [www.zekler.com/doc](http://www.zekler.com/doc)

They need to be worn against solid and liquid nonvolatile particles that do not exceed the amount of particles in the inhalable dust.

Limitations in the intended use

The half mask must not be used as protection against gases, vapours or chemical, biological, radioactive and nuclear warfare agents.

The oxygen content of the ambient air must not drop below the following limit values:

10 vol.-% in Europe except UK, Ireland, Poland, Italy, Spain, Portugal, Belgium, UK, Australia and New Zealand.

For other countries, see the national regulations

Never enter unventilated tanks, pits, canals etc. when wearing half masks.

The half masks may be used for a maximum one work shift (8 hours) at a time.

The chapter "Additional information" contains recommendations for use against infectious germs and biologically harmful substances is possible. Information on this topic is either contained in the instructions for use or the relevant national regulations.

The maximum concentration of the pollutants (esp. the type and concentration of pollutants) must be known. The maximum permitted concentration of the pollutants in the ambient air must not be exceeded.

Observe the limit values and limitations of use for the various half masks:

The half masks have been tested and approved in accordance with (EU) 2016/425 and EN

